



# Mill Tips to Prevent Chatter

Scan code to get the latest version of this document



Translation Available




## INTRODUCTION

Consider the overall job when you have a problem with chatter. Chatter always comes down to these aspects of the application:


### Program

Toolpath Type  
Feeds and Speeds (Chip Load)  
Width of Cut • Depth of Cut




### Tool Selection

Length • Width • Flutes • Geometry




### Workholding

Secure to the Table  
Secure to the Part




Compromises required in one aspect of the job will require adjustments to the other aspects of the job.

## Program




### Example:

Toolpaths with slotting and large corner engagement can cause chatter at a given speed/feed combination. Note how tool engagement increases through the internal corner [1] and in a slot cut [2].




## Toolpath Types

With a conventional toolpath, cutting forces increase as tool engagement increases with the direction changes.



Constant engagement toolpaths do not require adjustments to speeds and feeds through direction changes.


## Tool Selection



### Tool Selection - Tool Length


If the cut chatters and reducing the tool length is practical, reduce the tool length. A 10% reduction in the length-to-diameter ratio results in a 25% increase in tool stiffness.

Unless absolutely necessary, the tool should not be more than 3 times longer than it is wide.



## Tool Length and Deep Pockets

Deep pockets require deviation from the normal length-to-diameter ratio for tools. Lower the cutting load with program adjustments: reduce the depth-of-cut, the width-of-cut, feed, or change to a constant-engagement toolpath.




## Tool Types

Use the highest-performance tool possible, ideally with variable helix and cutting angles. High-performance tooling uses tool geometry designed to dampen the vibrations that cause chatter.

---

## Workholding



## Workholding Example:

Fragile workholding, a long, skinny part, overhangs, etc.—Lower the cutting load through adjustments to the tool selection or program. Stiffen the workholding with supports if possible.